

2022 Ford E-Transit

Weak Key Fob – Failure to Recognize



When E-Transit proximity Key Fob Batteries become weak the vehicle may have difficulty acknowledging its presence and not start.

Placing the Key Fob in the designated area will aid in starting the vehicle.

The designated area in the E-Transit is in the tray on top of the dashboard.



Immediately replace the weak Key Fob Battery