

2022 Ford F-150 Lightning EV

Weak Key Fob – Failure to Recognize



When F-150 Lightning proximity key fob batteries become weak, the vehicle may have difficulty acknowledging its presence and not start.

Placing key fob in the designated area will aid in starting the vehicle.

The designated area in the F-150 Lightning is in the rear cup holder in the center console.



Immediately replace the weak key fob battery.